Suzanne Steab - April 2011 Inspection Reports

From:

Karl Houskeeper

To:

JohnGefferth@consolenergy.com; PeterBehling@consolenergy.com; SteveBe...

Date:

5/4/2011 3:18 PM

Subject:

April 2011 Inspection Reports

CC:

ANGELANANCE@utah.gov; DARONHADDOCK@utah.gov; SUZANNESTEAB@utah.gov

Attachments: Hidden Valley April 2011.pdf; Emery April 2011.pdf

Attached are the April 2011 inspection reports for Hidden Valley and Emery.

Thanks,

Karl



GREG BELL

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Division of Oil, Gas and Mining

JOHN R. BAZA Division Director

Representativ	es Present During the Inspection:
Company	Peter Behling
OGM	Karl Houskeeper

Inspection Report

Permit Number:	C0150007
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, April 12, 2011
Start Date/Time:	4/12/2011 8:00:00 AM
End Date/Time:	4/12/2011 12:00:00 PM
Last Inspection:	Wednesday, March 02, 2011

Inspector: Karl Houskeeper. Weather: Clear, Temp. 43 Deg. F. InspectionID Report Number: 2710

Accepted by: jhelfric

Permitee: CONSOLIDATION COAL CO Operator: CONSOLIDATION COAL CO Site: HIDDEN VALLEY MINE

Address: PO BOX 566, SESSER IL 62884

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

960.00	Total Permitted
6.70	Total Disturbed
6.70	Phase i
	Phase II
	Phase III

			· ·
	Federal	¥	Underground
	State		Surface
	County		Loadout
¥	Fee		Processing
	Other		Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Karl R. Nousbuper

Date

Karl Houskeeper,

Inspector ID Number: 49

Permit Number: C0150007 Inspection Type: PARTIAL

Inspection Date: Tuesday, April 12, 2011

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 For PARTIAL inspections check only the elements evaluated.
 Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
 Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1,	Permits, Change, Transfer, Renewal, Sale		Cl	1	
2.	Signs and Markers	~	freedom.	¥	
3.	Topsoil	[]			
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	1		9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	\square
4.c	Hydrologic Balance: Other Sediment Control Measures			D	
4.d	Hydrologic Balance: Water Monitoring	V		Y	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				1000
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage		(man =)		
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading			1	
13.	Revegetation				
14.	Subsidence Control		At the	Ű	
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing)		
16.b	Roads: Drainage Controls				F
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations			andrew 1	Park 1
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other		/*****		f"]

Inspection Continuation Sheet

Permit Number: C0150007 Inspection Type: PARTIAL

Inspection Date: Tuesday, April 12, 2011

Page 3 of 3

2. Signs and Markers

Mine identification sign is located at the point of public access to the permit area. The sign contains the required information.

4.d Hydrologic Balance: Water Monitoring

Well HV-06-02 had a leak. Ground around the well was saturated. Efforts are being made to find the source of the leak, potentially a broken sampling pipe. A cow entered the soaked and saturated area around the well and became stuck and died. No identification remains on the cow to determine the owner.